

To: Daly, Eric[Daly.Eric@epa.gov]
From: Daly, Eric
Sent: Thur 6/8/2017 4:30:28 PM
Subject: FW: NFB GNBC Office Area

Hi Frank:

Attached are photos of what GNBC John pointed out to me.


1. Temporary door is still on
2. Broken tile by bathroom drain
3. Window well sheetrock is pitted (New window still needs to be installed so not sure if they were waiting for the installation to do last spackle and paint)
4. Dented ceiling tile
5. Apparently visible seams on drywall (wall on Rapid Bowling alley side)
6. They wanted a door stop on the new interior door











Regards,

Eric

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin

Eric M. Daly

On-Scene Coordinator/Radiological Response Specialist

US Environmental Protection Agency- Region II

ERRD/RPB/PPS

2890 Woodbridge Avenue

Edison, NJ 08837

daly.eric@epa.gov

908-420-1707